



C9C  
MT

I hereby certify that this correspondence  
is being deposited with the United States  
Postal Service as first class mail in an  
envelope addressed to:

Commissioner for Patents  
United States Patent & Trademark Office  
Mail Stop: Certificate of Correction  
P.O. Box 1450  
Alexandria, VA 22313-1450, on 3/16/05

Michael P. Pinianni  
DATE March 16, 2005

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Examiner: Basil S. Katcheves

Group Art Unit: 3635

In re application of

Paul W. Brown

Serial No.: 10/044,660

Filed: January 19, 2002

Patent No. 6,810,634 B1

Issued: November 2, 2004

Certificate  
MAR 24 2005  
of Correction

: METHOD OF RESISTING CORROSION  
: IN METAL REINFORCING ELEMENTS  
: CONTAINED IN CONCRETE AND  
: RELATED COMPOUNDS AND  
: STRUCTURES

: ATTORNEY DOCKET: 287122-00001-1

03/21/2005 HDEHES1 00000010 022556 6810634

01 FC:1811 100.00 DA

LETTER

600 Grant St., 44th Floor  
Pittsburgh, PA 15219  
March 16, 2005

Commissioner for Patents  
United States Patent & Trademark Office  
Certificate of Correction Branch  
Mail Stop: Certificate of Correction  
P.O. Box 1450  
Alexandria, VA 22313-1450

Sir:

In comparing the above-identified original patent document with the original  
papers filed in the Patent and Trademark Office, we have noted twelve (12)

typographical errors which should be charged to our Deposit Account No. 02-2556 in the amount of One Hundred Dollars (\$100).

It is respectfully requested that a Certificate of Correction be issued to correct these printing errors in the above-identified patent.

Respectfully submitted,

A handwritten signature in black ink, appearing to read "Tara L. Pfaeffle", followed by a horizontal line extending to the right.

Tara L. Pfaeffle

Registration No. 52,605

Attorney for Applicant

(412) 566-5941

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,810,634 B1

DATED : November 2, 2004

INVENTOR(S) : Paul W. Brown

It is certified that errors appear in the above-identified patent and that said Letters Patent should be corrected as shown below:

Col. 1, line 50, after "sea walls", insert a ---.

Col. 3, line 47, delete "to" prior to "provide".

Col. 3, line 65, "rehabilitated through by sequestering" should read --rehabilitated by sequestering--.

Col. 4, line 7, "invention and facilitates" should read --invention facilitates--.

Col. 6, line 48, "seal" should read --steel--.

Col. 7, line 23, after "presence", insert --of--.

Col. 8, line 10, after "presence", insert --of--.

Col. 9, line 62, "Referred" should read --Referring--.

1 of 2

**MAILING ADDRESS OF SENDER:**

Sally Novosel, Docket Administrator  
ECKERT SEAMANS CHERIN & MELLOTT, LLC  
600 Grant Street, 44th Floor  
Pittsburgh, PA 15219

**PATENT NO. 6,810,634**

No. of add'l. copies

@ 50¢ per page

⇒

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,810,634 B1

DATED : November 2, 2004

INVENTOR(S) : Paul W. Brown

It is certified that errors appear in the above-identified patent and that said Letters Patent should be corrected as shown below:

Col. 10, line 36, "structural" should read --structure will--.

Col. 11, line 13, "NaAlO<sub>4</sub>" should read --NaAlO<sub>2</sub>--.

Col. 11, lines 15 and 19, "2NaAlO<sub>4</sub>" should read --2NaAlO<sub>2</sub>--.

2 of 2

**MAILING ADDRESS OF SENDER:**

Sally Novosel, Docket Administrator  
ECKERT SEAMANS CHERIN & MELLOTT, LLC  
600 Grant Street, 44th Floor  
Pittsburgh, PA 15219

**PATENT NO. 6,810,634**

No. of add'l. copies

@ 50¢ per page

⇒